



Full Speed Ahead (FSA) Gossamer Pro AGX+ CK-6037 crankset Recall

Full Speed Ahead (FSA) has received reports of crank arms becoming loose or “wobbly” and detaching from the crank/spindle, posing fall and injury hazards to consumers. Only the drive-side crank arm is susceptible to bonding failure. Consumers should immediately stop using the bicycles with the recalled cranksets and contact Full Speed Ahead for instructions on how to receive free dealer installation of a new replacement crankset.



Compliance Testing

Prior to receiving reports, the crankset passed all international ISO testing standards.

Inspection of Crankset

Inspect Gossamer Pro AGX+ CK-6037 cranksets and bicycles pre-assembled by OEM with Gossamer Pro AGX+ CK-6037 cranksets that may be within the serial number range stated below. FSA will be requesting all cranksets within serial number ranges starting with B1, B2, and B3 to be returned to FSA for replacement. The serial number range is shown highlighted below. The cranksets were sold on Cannondale, Canyon, Marin Haro, Fuji and Pinarello gravel brand bicycles.





Corrective Action Plan

FSA is preparing to replace cranksets for consumers, dealers, distributors, and bicycle manufacturers (referred to as OEM) with the Gossamer Pro AGX+ CK-6037 cranksets. FSA will be requesting all cranksets within serial number ranges starting with **B1, B2 and B3** to be returned to FSA for replacement. Shipping costs associated with returning the cranksets will be paid by FSA, please contact your FSA representative for specific details.

Distributors and OEM: distributors and bicycle manufacturers who pre-assembled Gossamer AGX+ CK-6037 cranksets on their bicycles (OEM) have been contacted by FSA to stop shipment of Gossamer AGX+ CK-6037 crankset inventory and bicycles built with Gossamer AGX+ CK-6037 cranksets. Inspection of distributor and OEM inventory has begun for cranksets that are within the prospective range. Any crankset within the prospective range will be replaced free of charge. Distributors and OEM are also requested to contact their dealers who have purchased the Gossamer AGX+ CK-6037 cranksets or bicycles with Gossamer AGX+ CK-6037 cranksets installed and request the dealers inspect their inventory and any cranksets purchased by consumers. Dealers will be able to contact FSA directly for replacement. Distributors and OEM need to call or contact the FSA local distributor and/or FSA directly for replacement cranksets.

Australia: please contact Leo Yip: leo@fullspeedahead.com