

# Product Safety Recall



**Carbon Forks** on certain 2017 Model year MERIDA Scultura bikes sold nation-wide between July 2016 and July 2017

**Defect** In some circumstances, the fork steerer tube of the full carbon fork has insufficient strength & the fork steerer tube might develop cracks below the stem or spacers.

## **Models subject to recall**

MY17 Scultura Disc 400 / Scultura Disc 400 Juliet

MY17Scultura 4000 / Disc 4000

MY17Scultura 4000 Juliet / Disc 4000

MY17Scultura 5000 / Disc 5000

MY17Scultura 6000

MY17Scultura Special Edition

**Hazard** If the defect occurs whilst the bicycle is in use, this could result in losing complete control of the bike, resulting serious injury or death.

**What to do** Consumers should stop using the bicycle immediately and contact their local Merida retailer to have a replacement fork fitted.

**Contact details** Contact Advance Traders on 1300 361 686 or go to [www.advancetraders.com.au](http://www.advancetraders.com.au)

See [www.recalls.gov.au](http://www.recalls.gov.au) for  
Australian Product Recall Information